



Place SAM 01 profile block on side spindle 2.
Place SAM 01 profile block on side spindle 3.
Place SAM 93 profile block on the first top spindle.
Place SAM 97 profile block on the bottom spindle.



PRINTED COPY UNCONTROLLED

MOULDER	5,6,7
PASSES	1
DRAWN BY	Bart Sobecki
DATE	31/08/2023
SCALE	1:1
REV:	1
AUTH:	
TOLERANCE	+/- 0.5MM

SAM[®]

Newpark Industrial Estate
Greystone Road, Antrim
BT41 2RU
T: +44 (0)28 9442 8288 F: +44 (0)28 9442 8244
E: team@samonline.co.uk
W: www.samonline.co.uk

PROFILE
SAM 5439