


Place SAM 01 profile block on side spindle 2.
 Place SAM 01 profile block on side spindle 3.
 Place SAM5650 on the first top spindle.



PRINTED COPY UNCONTROLLED

MOULDER	ANY
PASSES	1
DRAWN BY	A.Fairley
DATE	02/05/2025
SCALE	1:1
REV:	1
AUTH:	
TOLERANCE	+/- 0.5MM



Newpark Industrial Estate
 Greystone Road, Antrim
 BT41 2RU
 T: +44 (0)28 9442 8288 F: +44 (0)28 9442 8244
 E: team@samonline.co.uk
 W: www.samonline.co.uk

PROFILE	
SAM5650	