


Place SAM 01 profile block on side spindle 2.
 Place SAM 01 profile block on side spindle 3.
 Place SAM5651 on the first top spindle.



PRINTED COPY UNCONTROLLED

MOULDER	ANY
PASSES	1
A.Fairley	REV: 2
02/05/2025	AUTH:
1:1	TOLERANCE +/- 0.5MM



Newpark Industrial Estate
 Greystone Road, Antrim
 BT41 2RU
 T: +44 (0)28 9442 8288 F: +44 (0)28 9442 8244
 E: team@samonline.co.uk
 W: www.samonline.co.uk

PROFILE	DRAWN BY	A.Fairley	REV: 2
SAM5651	DATE	02/05/2025	AUTH:
	SCALE	1:1	TOLERANCE +/- 0.5MM