


Place SAM1960 T2 on side spindle 2.
 Place SAM 01 on side spindle 3.
 Place SAM1960 T1 on first top spindle.



PRINTED COPY UNCONTROLLED

AREA MACHINED AWAY: 331.59 MM SQUARE

		MOULDER	ANY	
		PASSES	1	
SAM MOULDINGS Newpark Industrial Estate Greystone Road Antrim BT41 2RU Tel :(028) 9442 8288 Fax :(028) 9442 8244 Website: www.sammouldings.co.uk Email: info@sammouldings.co.uk	PROFILE	DRAWN BY	P Millar	REV: 1
	SAM 1960	DATE	11/12/07	AUTH:
		SCALE	1:1	TOLERANCE +/- 0.5MM