



A = mm
 B = Degrees
 C = mm
 D = mm
 E = mm
 F = mm

PRINTED COPY UNCONTROLLED

Please tick in box - Is groove a visible top surface for priming YES NO

MOULDER	ANY
PASSES	1

<h1 style="text-align: center;">SAM MOULDINGS</h1> <p style="text-align: center;">Newpark Industrial Estate Greystone Road Antrim BT41 2DU Tel : (028) 9442 8288 Fax : (028) 9442 8244 Website: www.sammouldings.co.uk Email: info@sammouldings.co.uk</p>	PROFILE	DRAWN BY	DAVID GILL	REV:
	SP 923	DATE	09/04/02	AUTH:
		SCALE	1:1	TOLERANCE +/- 0.5MM